

Machine & Equipment Labels (Continued)

 <p>⚠ DANGER Defective equipment.</p> <p>86792 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Disconnect before servicing.</p> <p>86793 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Do not climb, sit, walk or ride on conveyor.</p> <p>86882 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Do not operate unless authorized.</p> <p>86796 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Do not operate without guards in place.</p> <p>86797 3-1/2" x 5" B-302 5/pk</p>
 <p>⚠ DANGER Do not operate without guards in place.</p> <p>86869 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Do not smoke eat or drink in this area.</p> <p>86899 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Ear protection required while operating this machine.</p> <p>86798 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Electrical hazard.</p> <p>86799 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Flammable</p> <p>86801 3-1/2" x 5" B-302 5/pk</p>
 <p>⚠ DANGER Follow confined space entry procedures before entering.</p> <p>86896 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Hard hat area.</p> <p>86804 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER High voltage inside.</p> <p>86861 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER High voltage.</p> <p>86871 5" x 3-1/2" B-302 5/pk</p>	 <p>⚠ DANGER High voltage.</p> <p>86860 3-1/2" x 5" B-302 5/pk</p>
 <p>⚠ DANGER High voltage. Entry by authorized personnel only.</p> <p>86877 5" x 3-1/2" B-302 5/pk</p>	 <p>⚠ DANGER High voltage. Do not enter.</p> <p>86862 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Hot.</p> <p>86808 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Keep away from machinery.</p> <p>86811 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Keep hands away.</p> <p>86891 3-1/2" x 5" B-302 5/pk</p>
 <p>⚠ DANGER Keep hands clear when equipment is running.</p> <p>86886 5" x 3-1/2" B-302 5/pk</p>	 <p>⚠ DANGER Moving machinery. Keep hands & feet clear.</p> <p>86894 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Moving machinery. Keep hands and feet clear.</p> <p>86874 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Never reach into moving machinery.</p> <p>86885 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Pinch point.</p> <p>86868 3-1/2" x 5" B-302 5/pk</p>
 <p>⚠ DANGER Proper eye protection required.</p> <p>86867 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Respirator required.</p> <p>86813 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Starts automatically.</p> <p>86863 3-1/2" x 5" B-302 5/pk</p>	 <p>DANGER STARTS AUTOMATICALLY</p> <p>86148 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER 440 Volts.</p> <p>60373 3-1/2" x 5" B-302 5/pk</p>
 <p>⚠ DANGER Watch your hands and fingers.</p> <p>86817 3-1/2" x 5" B-302 5/pk</p>	 <p>⚠ DANGER Watch your hands and fingers.</p> <p>86887 5" x 3-1/2" B-302 5/pk</p>	 <p>⚠ DANGER Wear face shield when using this equipment.</p> <p>86818 3-1/2" x 5" B-302 5/pk</p>	 <p>DANGER HIGH VOLTAGE AUTHORIZED PERSONNEL ONLY PELIGRO ALTO VOLTAJE SOLO PERSONAL AUTORIZADO</p> <p>86235 5" x 3-1/2" B-302 5/pk</p>	 <p>DANGER HIGH VOLTAGE AUTHORIZED PERSONNEL ONLY PELIGRO ALTO VOLTAJE SOLO PERSONAL AUTORIZADO</p> <p>86234 5" x 3-1/2" B-302 5/pk</p>