## **Splice Cap Crimp Connectors**

- · Designed for making fast, permanent, pressure-type connections
- · Solid copper sleeves require less crimping pressure and resist corrosion in harsh environments
- UL 486C Listed and CSA C22.2 #188 Certified; comply with Federal Specification W-S-61D

Description	Wire Combination Range	Quantity	Cat. No.
Copper Crimp Connector	600V* 18 to 10 AWG Min. 2 #18, Max. 4 #12	Bag of 100	2006S
		Bag of 1,000	2006SB
	600V* 14 to 4 AWG Min. 2 #10, Max. 2 #6	Bag of 50	2011S
		Bag of 500	2011SB

\*1,000V maximum in fixtures and signs.

# Splice Cap Insulators

- · Convenient, safe and fast installation
- Snap-on nylon construction
- Rated at 105°C (221°F) 600V (1,000V maximum in fixtures and signs)

	-	
Description	Quantity	Cat. No.
For use on Connector Model 2006S	Box of 100	2007
	Bag of 1,000	2007B
For use on Connector Model 2011S	Box of 50	2014
	Bag of 500	2014B

### Set Screw Wire Connectors

- · Eliminates need for restripping wire each time connection is disturbed
- Solid brass sleeves
- · Set-screw easily and securely applies maximum compression to conductors to ensure a vibration-resistant splice
- Permits fast visual inspection of splice
- Tough, flame-retardant shell rated at 150°C (302°F)
- UL Listed to 486C and CSA Certified to C22.2 #188; comply with Federal Specification W-S-610E

Ś
LISTED Wire Connector

LISTED

Wire Connector

Model	Wire Combination Range	Quantity	Cat. No.
10	300V	Box of 100	30-210
	22 thru 10 AWG Min. 1 #20 w/1 #22 - Max. 2 #14 w/1 #16	Carton of 1,000	30-310
11	600V	Box of 100	30-211
	22 thru 10 AWG Min. 1 #14 w/1 #20 - Max. 3 #14 w/2 #18	Carton of 1,000	30-311
22	600V 20 thru 10 AWG Min. 1 #16 w/3 #18 – Max. 2 #10 w/1 #12	Box of 100	30-222
		Carton of 1,000	30-322

#### Set Screw Holder

- · Convenient tool for holding and tightening set-screw connectors
- Accepts IDEAL Models 11 and 22 set-screw connectors



K-2422

### WIRE TERMINATION A-33

For Connector Models 11 & 22

Description